

CERTIFICATE OF COMPLIANCE

Certificate Number 20170307-E486341
Report Reference E486340-20161026
Issue Date 2017-March-07

Issued to: SHANGHAI AEROSPACE AUTOMOBILE
ELECTROMECHANICAL CO LTD
The 8Th Floor Of Spaceflight Building
222 Caoxi Rd
Shanghai, 200235 CHINA

**This is to certify that
representative samples of**

PHOTOVOLTAIC MODULES AND PANELS WITH
SYSTEM VOLTAGE RATINGS OVER 600 VOLTS
See Addendum Page

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety:

UL 1703 - Standard for Safety for Flat-Plate Photovoltaic
Modules and Panels
ULC/ORD-C1703-01, Flat-Plate Photovoltaic Modules and
Panels

Additional Information:

See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20170307-E486341
Report Reference E486340-20161026
Issue Date 2017-March-07

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Photovoltaic Module, Models

HT36-156P-125, HT36-156P-130, HT36-156P-135, HT36-156P-140, HT36-156P-145, HT36-156P-150, HT36-156P-155, HT36-156P-160, HT36-156P-165, HT36-156P-170, HT36-156P-175;

HT48-156P-170, HT48-156P-175, HT48-156P-180, HT48-156P-185, HT48-156P-190, HT48-156P-195, HT48-156P-200, HT48-156P-205, HT48-156P-210, HT48-156P-215, HT48-156P-220, HT48-156P-225, HT48-156P-230, HT48-156P-235;

HT54-156P-190, HT54-156P-195, HT54-156P-200, HT54-156P-205, HT54-156P-210, HT54-156P-215, HT54-156P-220, HT54-156P-225, HT54-156P-230, HT54-156P-235, HT54-156P-240, HT54-156P-245, HT54-156P-250, HT54-156P-255, HT54-156P-260;

HT60-156P-210, HT60-156P-215, HT60-156P-220, HT60-156P-225, HT60-156P-230, HT60-156P-235, HT60-156P-240, HT60-156P-245, HT60-156P-250, HT60-156P-255, HT60-156P-260, HT60-156P-265, HT60-156P-270, HT60-156P-275, HT60-156P-280, HT60-156P-285, HT60-156P-290;

HT72-156P-255, HT72-156P-260, HT72-156P-265, HT72-156P-270, HT72-156P-275, HT72-156P-280, HT72-156P-285, HT72-156P-290, HT72-156P-295, HT72-156P-300, HT72-156P-305, HT72-156P-310, HT72-156P-315, HT72-156P-320, HT72-156P-325, HT72-156P-330, HT72-156P-335, HT72-156P-340, HT72-156P-345, HT72-156P-350.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

